



FIG.1


FIG.2



Horizontal Axis: Time

FIG.3





4/12





FIG.5

Current Passing Through Switch 102



Current Passing Through Secondary Winding Of Transformer 105





FIG.6









FIG.8



Horizontal Axis: Time

FIG.9








Horizontal Axis: Time

10/12










Oblon, Spivak, et al. 703-413-3000 Docket # 294482us Sheet 11 of 12

11/12

FIG.11

Transformer 105



12/12

